

FIG.1




FIG. 2




FIG.3




FIG. 4




FIG.5




FIG.6





FIG.7



ST3

FIG.8





FIG.9

[MEASUREMENT/CUTTING]



[MEASUREMENT/CUTTING]




FIG.11

[MEASUREMENT/CUTTING]





FIG.12

[END PROCESSING]

ST2



[MEASUREMENT/CUTTING]

ST1




FIG.13

[END PROCESSING]

ST2




FIG.14




FIG.15

[TERMINAL CONNECTION]




FIG.16

[TERMINAL CONNECTION]

ST3




FIG.17

[INSPECTION]

ST4




FIG.18

[TRANSFER]

ST5

